LIGHTNING SURGE PROTECTOR FOR STRAIN GAUGE (ultra-slim)

MODEL

MD7LC

BEFORE USE

Thank you for choosing M-System. Before use, please check contents of the package you received as outlined below. If you have any problems or questions with the product, please contact M-System's Sales Office or representatives.

■ PACKAGE INCLUDES:

Surge protector.....(1)

■ MODEL NO.

Confirm Model No. marking on the product to be exactly what you ordered.

■ INSTRUCTION MANUAL

This manual describes necessary points of caution when you use this product, including installation, connection and basic maintenance procedures.

When using this product in potentially explosive atmosphere or hazardous (classified) location, you have to follow the safety procedure to install it. Please refer to "SAFE IN-STALLATION MANUAL" for each type of certification.

LIMITATION APPLICABLE TO M-RESTER

The M-RESTER will protect electronics equipment from damage caused by lightning by absorbing most of the surge voltages.

However, M-RESTER may not be effective against certain extremely high voltages caused by a direct or almost direct hit by lightning.

M-RESTER must be installed according to this installation / instruction manual.

GENERAL

■ FUNCTION & FEATURES

- High discharge current capacity 20 kA (8 / 20 µs), 1 kA (10/350 us)
- Ultra-thin 7-mm-wide module can be mounted in high density
- Excellent protection employing multi-stage SPD circuits
- DIN rail mounting and grounding
- Shield terminal provided
- Protects strain gauges and transmitters

■ SPECIFICATIONS

See Table 1.

Table 1. Specifications

MODEL NO.		MD7LC-0	MD7LC-1	
Max. continuous operating voltage (Uc)	Output voltage	±0.2V		
	Excitation	1	15V	
	Line to Earth*1	±15V		
Voltage protection level (Up)	Output voltage	±15V @0.2kV (1.2 / 50 µs)	±40V @6kV (1.2 / 50 µs)	
	Excitation	30V @0.2kV (1.2 / 50 μs)	50V @6kV (1.2 / 50 μs)	
	Line to Earth*1	±30V @0.2kV (1.2 / 50 µs)	±50V @6kV (1.2 / 50 µs)	
Leakage current @Uc	Output voltage	≤0.:	≤0.2µA	
	Excitation	≤2µA		
	Line to Earth*1	≤2µA		
Response time		≤4 nsec.		
Max. discharge current (Imax)		100A (8 / 20 μs)	20kA (8 / 20 μs), 1kA (10 / 350 μs)	
Nominal current (I _N)			250mA	
Internal series resistance			1.5Ω ±10% per line	

^{*1.} Measured across the terminal 2 and DIN rail, the terminal 7 and DIN rail.



POINTS OF CAUTION

■ ENVIRONMENT

- Indoor use.
- When heavy dust or metal particles are present in the air, install the unit inside proper housing with sufficient
- Do not install the unit where it is subjected to continuous vibration. Do not subject the unit to physical impact.
- \bullet Environmental temperature must be within -25 to +85°C (-13 to +185°F) with relative humidity within 30 to 90% RH in order to ensure adequate life span and operation.
- This unit needs a DIN rail as earth grounding bar. Oxide coating of an aluminium rail may lower the electric conductivity between this module and the ground. Use a steel or copper rail.


■ DIELECTRIC STRENGTH TESTING

• The surge protector starts discharging when a voltage greater than 15V is applied between lines and earth. Remove the grounding wire before conducting a test. Be sure to return the wire after the test.

■AND

- We recommend that you keep spare surge protectors so that you can replace them when necessary.
- Lightning surge can enter not only through signal lines but also through power supply lines. We recommend that you also use the Lightning Surge Protector for Power Lines for adequate protection.

COMPONENT IDENTIFICATION




INSTALLATION

Mount the unit on a DIN rail. Once installed, do not move it to another DIN rail.


■ MOUNTING THE UNIT ON A DIN RAIL

- A) Hang the upper hook of the DIN rail mounting adaptor at the rear side of unit, on the DIN rail.
- B) Push in the lower in keeping pressing the unit to the DIN
- C)DIN rails generally have slight individual variability in size. If you find it difficult to push in the lower part, go back to (A) and hang the upper part more deeply onto the rail and try (B) again.



■ REMOVING THE UNIT

- A) Push down the spring loader utilizing a minus screwdriv-
- B)Confirm that it is pulled enough down and pull out the lower part of the unit.
- C) Detach the upper part from the DIN rail.




TERMINAL CONNECTION

Connect the unit as in the diagram below.


Be sure to ground the DIN rail on which the unit is mounted and cross-wire between the rail and FG terminal of the protected device as shown in Figure 1 in order to equalize the earth potential.

When the unit is connected with a device which has no FG terminal, ground the surge protector only.

■ EXTERNAL DIMENSIONS unit: mm (inch)



■ Figure 1. GROUNDING




Cross-wire from the DIN rail to the metal housing of the protected device to equalize the ground potential.

Ground only the surge protector when the protected device has no grounding terminal.


Note: No need of cross wiring for the protected devices connected to the

■ CAUTION WHEN WIRING



Hold the module steady at the front when you tighten/loosen screw terminals.

■ CONNECTION DIAGRAM



- *1. Without the MD7G, cross-wire between the DIN rail and the metal housing of the protected device to equalize the earth potential.
- *2. Oxide film on the surface of an aluminium rail may lower the electric conductivity between this module and the ground. Use a steel or copper rail.
- *3. Be sure to ground the DIN rail. Recommended grounding resistance ≤100Ω.

WIRING INSTRUCTIONS

■ EURO TERMINAL

Torque: 0.3 N·m

Applicable wire size: 0.2 - 2.5 mm²

Stripped length: 8 mm

MAINTENANCE

Check surge protectors periodically. Many cases of lightning are ignored, and even lightning at a far distance often causes inductive surges.

We recommend that you check your surge protector about twice a year, before and after the rainy season. Check whenever you experience a strong lightning occurrence. Checking procedure is explained in the following:

■ CHECKING

WIRING

- 1) Make sure that wiring is done as instructed in the connection diagram.
- 2) Make sure that the DIN rail is connected to the metal enclosure of protected device.
- 3) Make sure that the surge protector is securely attached to the DIN rail, and that the rail is grounded to earth.

■ DISCHARGE ELEMENT

- 1) Remove all wiring connected to the surge protector when you test the module.
- 2) Check resistance across the following terminals on the high resistance range of multimeter (measuring current $\leq 0.25 \,\mu\text{A}$) and confirm no conduction.

Terminals (4) - (5), (6) - (8),

$$(5) - (DIN rail), (8) - (DIN rail)$$

The tester should show 1 M Ω or greater for the terminals (6) – (8), 10 M Ω or greater for other sets of terminals. When measuring across (4) - (5), connect the tester's probe so that the positive voltage is applied to (4).

- 3) Confirm conduction across the same terminals with a $500\,$ $V DC 1000 M\Omega$ insulation tester. The tester should show 20 MΩ or less.
- 4) If any of the above tests shows negative, replace the surge protector.

