

### DATA SHEET

# ) - KH 1

### **KISTOCK Data logger HVAC range - Temperature/Humidity**

056 222 38 18 mailbox@sentronic.com www.sentronic.com



Integrated software for configuration and visualisation in PDF format

- Software for configuration and data visualisation freely downloadable
- Software for configuration and data processing available as option
- Storage capacity of 50 000 points



- Up to 2 recordable parameters
- 2 configurable setpoint alarms •
- 1 line LCD screen
- IP 65 (KT 120) and IP 20 (KH 120) housing •
- Integrated adjustment certificate in PDF

### **Technical specifications**

| ······································  |   |  |
|---|---|--|
|   | KT 120  | KH 120   |
| Units displayed                         | °C, °F  | °C, °F, % RH   |
| Resolution                              | 0.1 °C, 0.1 °F                                      | 0.1 °C, 0.1 °F, 0.1% RH  |
| External input                          | USB connector                                       |  |
| Internal sensor                         | Temperature   | Temperature, humidity  |
| Type of sensor                          | NTC   | Temperature: NTC<br>Humidity: Capacitive   |
| Measuring range                         | From -40 to +70 °C                                  | Temperature: from -20 to +70 °C<br>Humidity: from 0 to 100 %RH   |
| Accuracies <sup>(1)</sup>               | ±0.4 ° from -20 to<br>70 °C<br>±0.8 °C below -20 °C | Temperature:<br>±0.4 °C from 0 to 50 °C<br>±0.8 °C below 0 °C or above 50 °C<br>Humidity <sup>(2)</sup> : ±2.5% RH<br>(from 5 to 95% RH, 15 °C to 25 °C) |
| Setpoint alarms                         | 2 setpoint alarms on each channel                   |  |
| Number of points                        | 50 000  |  |
| Frequency of<br>measurement             | From 1 minute to 24 hours                           |  |
| Operating<br>temperature <sup>(3)</sup> | From -40 to +70 °C                                  | From -20 to +70 °C   |
| Storage temperature                     | From -40 to +85 °C                                  |  |
| Battery life                            | 3 years <sup>(4)</sup>                              | 500 days <sup>(4)</sup>  |
| European directives                     | 2011/65/EU RoHS II; 2012/19/EU WEEE;                |  |

### **European directives**

2014/30/EU EMC; 2014/35/UE

SENTRONIC AG

### Housing

| 100 x 42.5 x 15.9 mm   |
|--|
| 53 g   |
| 1 line LCD screen<br>Dimensions of screen:<br>32 x 25.5 mm                                       |
| 1 OK key<br>1 Selection key  |
| Compatible with food industry<br>environment. ABS housing  |
| IP65: KT 120. IP20: KH 120   |
| 1 USB A male input   |
| 1 x CR2450 (button battery <sup>(5)</sup> )  |
| Air and neutral gases<br>Hygrometry: in non condensing<br>conditions<br>Maximum altitude: 2000 m |
|  |

<sup>(1)</sup> All accuracies indicated in this document were stated in laboratory conditions and can be guaranteed for measurement carried out in the same conditions, or carried out with calibration compensation.

<sup>(2)</sup> Factory calibration uncertainty: ±0.88% RH; Temperature dependence: ±0.04 x (T-20) % RH (if T < 15 °C or T > 25 °C).

 $^{(3)}$  The screen can be hard to read, and its display speed often slows down at temperatures lower than 0 °C. This has no effect on the accuracy of measurements. (4) On the basis of 1 measurement each 15 minutes at 25 °C.

<sup>(5)</sup> The battery must be in compliance with the IEC 60086-4 standard.



### DATASET is finished.

Indicates that one value is being recorded. It flashes: the DATASET did not start already.

Flashing slowly: DATASET is between 80 and 90% of the storage capacity. Flashing quickly: DATASET is between 90 and 100% of the storage capacity.

Constant: storage capacity full.

Indicates the alarm action

type: rising or falling action.

The displayed values are the recorded maximum/minimum values for the displayed channels.

**BRE** Constant: indicates that the batteries have to be replaced to be replaced.

Calibration

easily.

12 Indicates the channel number which is measuring.

°C: Temperature in °Celsius °F: Temperature in °Fahrenheit %RH: Relative humidity (KH 120)

### Dimensions (mm)



## PC connection input

Connections



### **Recorder function**

The KISTOCK allows to record the values measured instantaneously, it records the values according to a predefined interval.

On the other hand, it is possible to operate continuously the KISTOCK thanks to a loop recording.

The measurement dataset can be launched:

- With a delayed start (with predefined date and time)
- · With the software
- With push-button

### Software



### KILOG LITE: freely downloadable software on sauermanngroup.com

Allows the data download (graphics and points statement) and the data logger configuration.



### Integrated software in PDF format

Enables to edit a dataset report and configure the data logger.

Use only with Adobe Acrobat Reader 9® software (or higher).

### Configuration and data processing software

KILOG software enables to configure, save and process your data in a very simple way. Software only: réf. KILOG-3-N.

### Accessories

1 CR2450 battery. Ref. KBL-2450





Only the accessories supplied with the device must be used

**Maintenance:** please avoid any aggressive solvent. Please protect the device from any cleaning produce containing formalin, that may be used for cleaning rooms and ducts.

### 6 types of dataset stop

You can stop your dataset:

• According to a date and time (if it was started the same way)

All the KISTOCK devices have an integrated adjustment certificate

in the memory in PDF format which can be visualised and printed

A calibration certificate is available as option in paper format.

- According to a recording duration
- According to a predefined number of recording points
- If the storage capacity of the memory is full

We recommend to carry out a yearly checking.

- With "Stop" option of the software
- By holding "OK" key during about 5 seconds, if this function has been previously activated by the software.

### Mounting

The KISTOCK data loggers have a magnetic mounting, so you can fix it easily.

**Replace the battery** 

1. Magnetic mounting

visible.

Warranty

•

2. Battery cover 3. Locking sign of the battery cover

long-term measurements. To replace the battery:

Unlock the battery cover.



Precautions for use: please always use the device in

defect (return to our After-sales service required).

\*On the basis of 1 measurement each 15 minutes at 25 °C. \*\*The battery must be in compliance with the IEC 60086-4 standard.

accordance with its intended use and within parameters described in the technical features in order not to compromise the protection ensured by the device.

Insert the battery (CR 2450 button battery\*\*) with the + pole

Replace the battery cover with the indicator in front of the

opened padlock and close it by turning it towards the right in order

KISTOCK data loggers have 1-year guarantee for any manufacturing

to make correspond the indicator with the closed padlock.



BE CAREFUL! Material damages can happen, so please apply the indicated precaution measures.



### 3 types of dataset start